

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Acura	CSX	08-11	7002	7020K	1212	2045K	42753-SNA-A83	NO	A0201	GQ4-36T
Acura	ILX	13-14	7002	7020K	5513	7000K	42753-TX6-A81	VS70		KR5S180052015B
Acura	MDX	04-06			1057	2000K	06421-S3V-A04	1096	A0201	T7B-2T
Acura	MDX	07-13			1209	1100K	42753-STK-A04	NO	A0201	PAXPMV107G
Acura	MDX	14			5512	7000K	42753-TX4-A51	VS70		KR5S180052015B
Acura	RDX	07-12			1209	1100K	42753-STK-A04	NO	A0201	PAXPMV107G
Acura	RDX	13-14			5512	7000K	42753-TX4-A51	VS70		KR5S180052015B
Acura	RL	05-08			1057	2000K	06421-S3V-A04	1096	A0201	T7B-2T
Acura	RL	09-12			1057	2045K	42753-SHJ-A53	NO	A0201	GQ4-35T
Acura	RLX	13-14			1214	2045K	42753-TY2-A51	NO	A0201	GQ4-37T
Acura	TL	05-08			1057	2000K	06421-S3V-A04	1096	A0201	T7B-2T
Acura	TL(Hi-Line)	09-14			1214	2045K	42753-TK4-A01/ 42753-TY2-A51	NO	A0201	GQ4-37T
Acura	TSX	07-14			1209	1100K	42753-TL2-A52	NO	A0201	PAXPMV107G
Acura	ZDX(Hi-Line)	10-13			1214	2045K	42753-TK4-A01/ 42753-TY2-A51	NO	A0201	GQ4-37T
Audi	Allroad(315 Mhz)	01-05			9004	1090K	4D0 907 275A	1092	E0101	OYGTSSRE3B
Audi	A6 Allroad(433 Mhz)	01-06			9001	1090K	4D0 907 275C	1092	E0101	OYGTSSRE4B
Audi	A6 Allroad(433 Mhz)	07-09			9007 or 9011	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	A6 Allroad(433 Mhz)-- Post June 2009	10			9011	1096	4F0 907 275D	1096	E0101	OYG TSSRE4TD
Audi	A3(315 Mhz)	06-11	7003	7020K	1053	1030K	1K0907253D	NO	E0101	KR5S120123
Audi	A4(433 Mhz)	05-08			9007 or 9011	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	A4 (315 Mhz)	09-11	7003	7020K	1053	1030K	1K0907253D	NO	E0101	KR5S120123
Audi	A5(315 Mhz)	08-11	7003	7020K	1053	1030K	1K0907253D	NO	E0101	KR5S120123
Audi	A6(315 Mhz)	02-04			9004	1090K	4D0 907 275A	1092	E0101	OYGTSSRE3B
Audi	A6(433 Mhz)	05-09			9007 or 9011	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	A6(433 Mhz)-- Post June 2009	10-12			9011	1096	4F0 907 275D	1096	E0101	OYG TSSRE4TD
Audi	A8(315 Mhz)	00-07			9004	1090K	4D0 907 275A	1092	E0101	OYGTSSRE3B
Audi	A8(433 Mhz)	00-12			9001	1090K	4D0 907 275C	1092	E0101	OYGTSSRE4B
Audi	Q5(315 Mhz)	09	7003	7020K	1053	1030K	1K0907253D	NO	E0101	KR5S120123
Audi	Q7(433 Mhz)	06-09			9007 or 9011	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	Q7(433 Mhz)-- Post June 2009	10-12			9011	1096	4F0 907 275D	1096	E0101	OYG TSSRE4TD
Audi	R8(433 Mhz)	08-09			9007 or 9011	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	R8(433 Mhz)-- Post June 2009	10-12			9011	1096	4F0 907 275D	1096	E0101	OYG TSSRE4TD
Audi	RS4(433 Mhz)	07-08			9007 or 9011	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	RS6(315 Mhz)	01-05			9004	1090K	4D0 907 275A	1092	E0101	OYGTSSRE3B
Audi	RS6(433 Mhz)	01-04			9001	1090K	4D0 907 275C	1092	E0101	OYGTSSRE4B
Audi	S4(433 Mhz)	05-07			9007 or 9011	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	S4(315 Mhz)	10-11	7003	7020K	1053	1030K	1K0907253D	NO	E0101	KR5S120123
Audi	S5(315 Mhz)	08-11	7003	7020K	1053	1030K	1K0907253D	NO	E0101	KR5S120123
Audi	S6(433 Mhz)	05-09			9007 or 9011	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	S6(433 Mhz)-- Post June 2009	10-12			9011	1096	4F0 907 275D	1096	E0101	OYG TSSRE4TD
Audi	S8(315 Mhz)	00-08			9004	1090K	4D0 907 275A	1092	E0101	OYGTSSRE3B
Audi	S8(433 Mhz)	00-09			9001	1090K	4D0 907 275C	1092	E0101	OYGTSSRE4B
Audi	TT(315 Mhz)	08-11	7003	7020K	1053	1030K	1K0907253D	NO	E0101	KR5S120123
Bentley	Continental GT	03-05			9001	1090K	4D0 907 275C	1092-1095		OYGTSSRE4B
Bentley	Continental GT (Post May 2005)	05-10			9007 or 9011	1090K	4F0 907 275B	1092-1095		OYG TSSRE4TB

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Bentley	Continental GT	11-14			9011	1096	4F0 907 275B	1096		OYG TSSRE4TD
Bentley	Azure	07-10			9007 or 9011	1090K	4F0 907 275B	1092-1095		OYG TSSRE4TB
Bentley	Azure	11-14			9011	1096	4F0 907 275B	1096		OYG TSSRE4TD
Bentley	Mulsanne	11-14			9011	1096	4F0 907 275B	1096		OYG TSSRE4TD
Bentley	Flying Spur	06-10			9007 or 9011	1090K	4F0 907 275B	1092-1095		OYG TSSRE4TB
Bentley	Flying Spur	11-14			9011	1096	4F0 907 275B	1096		OYG TSSRE4TD
BMW	1 Series (433 Mhz)	07-10			1027	1090K	36 23 6 781 847	1092-1095	E0201	OYGTSSRE4TC
BMW	1 Series(433 Mhz (Post Sept, 2010)	11-13			9012	1096	36 10 6 856 227	1096	E0201	OYGTSSRE4DB
BMW	3 Series (315 Mhz)	00-04			9004	1090K	36 11 8 378 681	1092-1095	E0201	OYGTSSRE3B
BMW	3 Series (433 Mhz)	00-04			9002	1090K	36 11 8 378 682	1092-1095	E0201	OYG TSSRE4B
BMW	3 Series (433 Mhz)	07-10			1027	1090K	36 23 6 781 847	1092-1095	E0201	OYGTSSRE4TC
BMW	3 Series(433 Mhz)-- Post September 2009	10-12			9012	1096	36 10 6 856 227	1096	E0201	OYGTSSRE4DB
BMW	3 Series(433 Mhz) (Post October 2011)	12-14			9017	1096	36 10 6 798 872	1096	E0201	OYGTSSRE4DB
BMW	4 Series (433 Mhz)	14			9017	1096	36 10 6 798 872	1096	E0201	OYGTSSRE4DB
BMW	5 Series (315 Mhz)	00-02			9004	1090K	36 11 8 378 681	1092-1095	E0201	OYGTSSRE3B
BMW	5 Series (433 Mhz)	02-05			9002	1090K	36 11 8 378 682	1092-1095	E0201	OYG TSSRE4B
BMW	5 Series (433 Mhz)	06-10			1027	1090K	36 23 6 781 847	1092-1095	E0201	OYGTSSRE4TC
BMW	5 Series(433 Mhz (Post Sept 2010)	11-14			9012	1096	36 10 6 856 227	1096	E0201	OYGTSSRE4DB
BMW	6 Series (433 Mhz)	06-10			1027	1090K	36 23 6 781 847	1092-1095	E0201	OYGTSSRE4TC
BMW	6 Series(433 Mhz (Post March 2011)	12-14			9012	1096	36 10 6 856 227	1096	E0201	OYGTSSRE4DB
BMW	7 Series (315 Mhz)	00-01			9004	1090K	36 11 8 378 681	1092-1095	E0201	OYGTSSRE3B
BMW	7 Series (433 Mhz)	02-05			9002	1090K	36 11 8 378 682	1092-1095	E0201	OYG TSSRE4B
BMW	7 Series (433 Mhz)	06-10			1027	1090K	36 23 6 781 847	1092-1095	E0201	OYGTSSRE4TC
BMW	7 Series(433 Mhz) (Post Sept 2010)	11-14			9012	1096	36 10 6 856 227	1096	E0201	OYGTSSRE4DB
BMW	M Series (433 Mhz)	06-10			1027	1090K	36 23 6 781 847	1092-1095	E0202	OYGTSSRE4TC
BMW	M Series (433 Mhz)	11-14			9012	1096	36 10 6 856 227	1096	E0202	OYGTSSRE4DB
BMW	X1 (433 Mhz)	12-14			9012	1096	36 10 6 856 227	1096	E0202	OYGTSSRE4DB
BMW	X3 (433 Mhz)	06-10			1027	1090K	36 23 6 781 847	1092-1095	E0202	OYGTSSRE4TC
BMW	X3(433 Mhz) (Post November 2010)	11-14			9012	1096	36 10 6 856 227	1096	E0202	OYGTSSRE4DB
BMW	X5 (433 Mhz)	01-04			9003	1090K	36 14 6 752 128	1092-1095	E0202	OYG TSSRE4PB
BMW	X5 (433 Mhz)	07-10			1027	1090K	36 23 6 781 847	1092-1095	E0202	OYGTSSRE4TC
BMW	X5(433 Mhz) (Post October 2010)	11-14			9012	1096	36 10 6 856 227	1096	E0202	OYGTSSRE4DB
BMW	X6 (433 Mhz)	08-11			1027	1090K	36 23 6 781 847	1092-1095	E0202	OYGTSSRE4TC
BMW	X6(433 Mhz) (Post October 2010)	11-14			9012	1096	36 10 6 856 227	1096	E0202	OYGTSSRE4DB
BMW	Z Series (433 Mhz)	06-10			1027	1090K	36 23 6 781 847	1092-1095	E0202	OYGTSSRE4TC
BMW	Z Series (433 Mhz)	11-14			9012	1096	36 10 6 856 227	1096	E0202	OYGTSSRE4DB
BMW	Alpina (433 Mhz)	07-08			9002	1090K	36 11 8 378 682	1092-1095	E0201	OYG TSSRE4B

****1091-1099-1099L are valve options on some special wheel packages.**

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Bugatti	Veyron	05-06			NA	1090K	NA	1092-1095		UNKNOWN
Buick	Allure	07-08	7001/HP	7020K	NA	1050K	15921013	NO	D0305	MRXGMX272RS
Buick	Allure	09	7001-R/HP-R	VS80	9153	VS950	12768826	VS950	D0305	MRXG53MA4S
Buick	Enclave	08	7001/HP	7020K	NA	1050K	15921013	NO	D0305	MRXGMX272RS
Buick	Enclave	09-14	7001-R/HP-R	VS80	9153	VS950	22853741	VS950	D0305	MRXG53MA4S
Buick	Encore	13-14	7001-R/HP-R	VS80	9153	VS950	22854866	VS950	D0305	MRXG53MA4S
Buick	LaCrosse	07-08	7001/HP	7020K	NA	1050K	15921013	NO	D0305	MRXGMX272RS
Buick	LaCrosse	09-14	7001-R/HP-R	VS80	9153	VS950	22854866	VS950	D0305	MRXG53MA4S
Buick	Lesabre	07	7001-R/HP-R	VS80	9153	VS950	25799331	VS950	D0322	MRXG53MA4S
Buick	Lucerne	07-11	7001-R/HP-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Buick	Rainier	06-07	7001/HP	7020K	9116	1070K	25774006	NO	D0321	MRXGMT51MAN
Buick	Rainier	07	7001-R/HP-R	VS80	9153	VS950	25799331	VS950	D0321	MRXG53MA4S
Buick	Regal	11-14	7001-R/HP-R	VS80	9153	VS950	22854866	VS950	D0305	MRXG53MA4S
Buick	Verano	12-14	7001-R/HP-R	VS80	9153	VS950	22854866	VS950	D0305	MRXG53MA4S
Cadillac	ATS	13	7001-R/HP-R	VS80	NEW	VS90	22959744	VS90	D0305	KR55WY8826
Cadillac	ATS	14	7001-R/HP-R	VS80	9153	VS950	13581558	VS950	D0319	MRXG53MA4S
Cadillac	ATS Sport	13	7001/HP	7020K	NEW	7020K	22959748	VS70		UNKNOWN
Cadillac	ATS Sport	14	7001/HP	7020K	9158	1070K	20964159	NO		MRXC53MA4S
Cadillac	CTS	04-07	7001/HP	7020K	9116	1070K	25774006	NO	D0305	MRXGMT51MAN
Cadillac	CTS	08-14	7001-R/HP-R	VS80	9153	VS950	13581558	VS950	D0319	MRXG53MA4S
Cadillac	CTS-V	09-10	7001/HP	7020K	NA	1050K	15268606	NO	D0319	MRXGMX272RS
Cadillac	CTS-V	11-14	7001/HP	7020K	9158	1070K	15268606	NO	D0319	MRXGMX272RS
Cadillac	Deville	01-05			9117	1080K	25773946	NO	D0305	MRXGMG2RCAM
Cadillac	DTS	06	7001/HP	7020K	9158	1070K	15268606	NO	D0305	MRXGMX272RS
Cadillac	DTS	07-11	7001-R/HP-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Cadillac	ELR	14	7001-R/HP-R	VS80	9153	VS950	22854866	VS950	D0305	MRXG53MA4S
Cadillac	Escalade-ESV-EXT	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
Cadillac	Escalade-ESV-EXT	05-06	7003	7020K	9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
Cadillac	Escalade-ESV-EXT	07	7001/HP	7020K	NA	2020K	15825475	NO	D0321	GQ428T
Cadillac	Escalade-ESV-EXT	07	7001/HP	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
Cadillac	Escalade-ESV-EXT	07-14	7001-R/HP-R	VS80	9153	VS950	13586335	VS950	D0305	MRXG53MA4S
Cadillac	Seville	01-04			9117	1080K	25773946	NO	D0305	MRXGMG2RCAM
Cadillac	SRX	04-06	7001/HP	7020K	9116	1070K	25774006	NO	D0305	MRXGMT51MAN
Cadillac	SRX	07-14	7001-R/HP-R	VS80	9153	VS950	12768826	VS950	D0305	MRXG53MA4S
Cadillac	STS	05-09	7001/HP	7020K	9076	1070K	25758220	NO	D0319	MRXGMX295FM
Cadillac	STS	09	7001/HP	7020K	9158	1070K	15268606	NO	D0319	MRXGMX272RS
Cadillac	STS	09-11	7001-R/HP-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Cadillac	XLR	04-09	7001/HP	7020K	9076	1070K	25758220	NO	D0305	MRXGMX295FM
Cadillac	XTS	13-14	7001-R/HP-R	VS80	9153	VS950	20922900	VS950	D0305	MRXG53MA4S
**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.										
Chevrolet	Avalanche	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
Chevrolet	Avalanche	05-06	7003	7020K	9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
Chevrolet	Avalanche	07	7001/HP	7020K	NA	2020K	15825475	NO	D0321	GQ428T
Chevrolet	Avalanche	07	7001/HP	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
Chevrolet	Avalanche	07-13	7001-R/HP-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Aveo	07-11			9153	VS950	25920615	VS950	D0303	MRXG53MA4S
Chevrolet	Camaro	10-14	7001-R/HP-R	VS80	9153	VS950	22854866	VS950	D0301	MRXG53MA4S
Chevrolet	Camaro-Sport	12-14	7001/HP	7020K	9158	1070K	20964159	NO		MRXC53MA4S

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Chevrolet	Caprice	11-12	7001/HP	7020K	9158	1070K	15268606	NO	D0319	MRXGMX272RS
Chevrolet	Captiva	12-14	7001-R/HP-R	VS80	9153	VS950	13586335	VS950	D0305	MRXG53MA4S
Chevrolet	Cobalt	08-10	7001/HP	7020K	NA	1050K	15268606	NO	D0319	MRXGMX272RS
Chevrolet	Cobalt	08-10	7001-R/HP-R	VS80	9153	VS950	12768826	VS950	D0319	MRXG53MA4S
Chevrolet	Colorado	07-12	7003	7020K	9131	1110K	15122618	NO	D0321	MRXGMT102PWM
Chevrolet	Corvette	97-00			8006	1077K	10438853	NO	D0314	MRXGMG2R3FM
Chevrolet	Corvette-C5-Z6	01-04			9117	1080K	25773946	NO	D0313	MRXGMG2RCAM
Chevrolet	Corvette-C6	05-09	7001/HP	7020K	9076	1070K	25758220	NO	D0305	MRXGMX295FM
Chevrolet	Corvette	10-14	7001/HP	7020K	9158	1070K	20925924	NO	D0305	MRXC53MA4S
Chevrolet	Cruze	11-14	7001-R/HP-R	VS80	9153	VS950	20922900	VS950	D0305	MRXG53MA4S
Chevrolet	Equinox	07-09	7001/HP	7020K	NA	1050K	15921013	NO	D0319	MRXGMX272RS
Chevrolet	Equinox	10-14	7001-R/HP-R	VS80	9153	VS950	22854866	VS950	D0301	MRXG53MA4S
Chevrolet	Express Series	08-09	7001HP	7020K	NA	1050K	15921013	NO	D0305	MRXGMX272RS
Chevrolet	Express Series 1500	10-14	7001-R/HP-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Express Series 2500/3500	10-14	7001HP-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	G Series	08	7001/HP	7020K	NA	1050K	15921013	NO	D0305	MRXGMX272RS
Chevrolet	HHR	08-09	7001/HP	7020K	9158	1070K	15268606	NO	D0319	MRXGMX272RS
Chevrolet	HHR	08-11	7001-R/HP-R	VS80	9153	VS950	25920615	VS950	D0319	MRXG53MA4S
Chevrolet	Impala	06-07	7001/HP	7020K	9158	1070K	15268606	NO	D0305	MRXGMX272RS
Chevrolet	Impala	07-14	7001-R/HP-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Malibu(< 10/14/07)	08	7001/HP	7020K	NA	1050K	15921013	NO	D0319	MRXGMX272RS
Chevrolet	Malibu	08-14	7001-R/HP-R	VS80	9153	VS950	13589255	VS950	D0319	MRXG53MA4S
Chevrolet	Monte Carlo	06-07	7001/HP	7020K	9158	1070K	15268606	NO	D0305	MRXGMX272RS
Chevrolet	Monte Carlo	07	7001-R/HP-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Chevrolet	Orlando	12	7001-R/HP-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Chevrolet	Silverado--All	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
Chevrolet	Silverado--All	05-06	7003	7020K	9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
Chevrolet	Silverado--1500	07	7001/HP	7020K	NA	2020K	15825475	NO	D0321	GQ428T
Chevrolet	Silverado--1500	07	7001/HP	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
Chevrolet	Silverado--1500	07-14	7001-R/HP-R	VS80	9153	VS950	13589255	VS950	D0305	MRXG53MA4S
Chevrolet	Silverado--2500/3500	07	7001HP	7020K	NA	2020K	15825475	NO	D0321	GQ428T
Chevrolet	Silverado--2500/3500	07	7001HP	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
Chevrolet	Silverado--2500/3500	07-15	7001HP-R	VS80	9153	VS950	13589255	VS950	D0305	MRXG53MA4S
Chevrolet	Sonic	12-14	7001-R/HP-R	VS80	9153	VS950	20922900	VS950	D0301	MRXG53MA4S
Chevrolet	Spark	13-14	7001-R/HP-R	VS80	9153	VS950	22854866	VS950		MRXG53MA4S
Chevrolet	SS	14	7001/HP	7020K	9158	1070K	20964159	NO		MRXC53MA4S
Chevrolet	SSR	06-07	7001/HP	7020K	9116	1070K	25774006	NO	D0321	MRXGMT51MAN
Chevrolet	Suburban	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
Chevrolet	Suburban	05-06	7003	7020K	9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
Chevrolet	Suburban--1500	07	7001/HP	7020K	NA	2020K	15825475	NO	D0321	GQ428T
Chevrolet	Suburban-1500	07	7001/HP	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
Chevrolet	Suburban--1500	07-14	7001-R/HP-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Suburban--2500	07	7001HP	7020K	NA	2020K	15825475	NO	D0321	GQ428T
Chevrolet	Suburban-2500	07	7001HP	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Chevrolet	Suburban--2500	07-13	7001HP-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Tahoe	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
Chevrolet	Tahoe	05-06	7003	7020K	9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
Chevrolet	Tahoe	07	7001/HP	7020K	NA	2020K	15825475	NO	D0321	GQ428T
Chevrolet	Tahoe	07	7001/HP	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
Chevrolet	Tahoe	07-15	7001-R/HP-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Trailblazer	06-09	7001/HP	7020K	9116	1070K	25774006	NO	D0321	MRXGMT51MAN
Chevrolet	Traverse	09-14	7001-R/HP-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Trax	14	7001-R/HP-R	VS80	9153	VS950	22854866	VS950	D0305	MRXG53MA4S
Chevrolet	Uplander	08-09	7001/HP	7020K	9158	1070K	15268606	NO	D0319	MRXGMX272RS
Chevrolet	Volt	10-14	7001-R/HP-R	VS80	9153	VS950	22854866	VS950	D0301	MRXG53MA4S
**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.										
Chrysler	200	11-14	7001/HP	7020K	1051	7000K	68078861AA	VS70	D0203	KR5S180052015B
Chrysler	300M(433 Mhz)	02-04	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
Chrysler	300(315 Mhz)	05-07	7001/HP	7020K	1051	1050K	68111696AA	NO	D0203	KR5S180052015B
Chrysler	300(433 Mhz)	08	7004	7020K	1043	1050K	68001698AB	NO	D0203	KR5S180052020A
Chrysler	300(433 Mhz)	09-10			9214	9066K	56029400AE	9066K	D0203	MRXMERCXTX1
Chrysler	300(433 Mhz)	11-14			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Chrysler	Aspen	07-09	7001/HP	7020K	1051 **	1050K or 9066K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Chrysler	Concorde(433 Mhz)	02-04	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
Chrysler	Crossfire	04-08	7004	7020K	9028	1080K	52088990AC	NO	Dealer Relearn	MRXTG224AM02
Chrysler	Crossfire	05	7001/HP	7020K	1051 **	1050K or 9066K	56053030AB	9066K	Dealer Relearn	KR5S180052015B OR MRXDCA315TX1
Chrysler	Pacifica	04	7004	7020K	9028	1080K	52088990AC	NO	D0203	MRXTG224AM02
Chrysler	Pacifica	04-05	7001/HP	7020K	1052	1050K	04727392AB	NO	D0203	KR5S120123
Chrysler	Pacifica	06-08	7001/HP	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Chrysler	Prowler	01			8004	1080K	4815132AB	NO	D0201	MRXPRAMTX
Chrysler	Prowler	02	7004	7020K	9028	1080K	52088990AC	NO	D0201	MRXTG224AM02
Chrysler	PT Cruiser	08-10	7001/HP	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Chrysler	Sebring	07-10	7001/HP	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Chrysler	Sebring	10	7001/HP	7020K	1051	7000K	68078861AA	VS70	D0203	KR5S180052015B
Chrysler	Town and Country	02-03	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
Chrysler	Town and Country	04-05	7001/HP	7020K	1052	1050K	04727392AB	NO	D0203	KR5S120123
Chrysler	Town and Country	06-07	7001/HP	7020K	1051	1050K	56053030AB	NO	D0203	KR5S180052015B
Chrysler	Town and Country	08-10	7004	7020K	1043	1050K	68001698AB	NO	D0203	KR5S180052020A
Chrysler	Town and Country	10	7004	7020K	1043	7000K	68078768AA	VS70	D0203	KR5S180052020A
Chrysler	Town and Country	11-14			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Chrysler	Voyager(433 Mhz)	02-03	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
**The 1050K is to be used on the Siemens sensors and the 2030K is to be used on the Schrader sensors.										
Dodge	Avenger	08-10	7001/HP	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Dodge	Avenger	10-14	7001/HP	7020K	1051	7000K	68078861AA	VS70	D0203	KR5S180052015B
Dodge	Caliber	07-10	7001/HP	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Dodge	Caliber	11-12	7001/HP	7020K	1051	7000K	68078861AA	VS70	D0203	KR5S180052015B
Dodge	Caliber--export	12	7004	7020K	1043	7000K	68078768AA	VS70	D0203	KR5S180052020A
Dodge	Caravan	02-03	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
Dodge	Caravan	04-05	7001/HP	7020K	1052	1050K	04727392AB	NO	D0203	KR5S120123
Dodge	Caravan	06-07	7001/HP	7020K	1051	1050K	56053030AB	NO	D0203	KR5S180052015B
Dodge	Challenger	08	7004	7020K	1043	1050K	68078768AA	NO	D0203	KR5S180052020A
Dodge	Challenger SRT	08-14			9214	9066K	56029400AE	9066K	D0203	MRXMERCXTX1
Dodge	Challenger	10-14			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Dodge	Charger	06-07	7001/HP	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Dodge	Charger	08	7004	7020K	1043	1050K	68001698AB	NO	D0203	KR5S180052020A
Dodge	Charger SRT	09-14			9214	9066K	56029400AE	9066K	D0203	MRXMERCCTX1
Dodge	Charger	10-14			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Dodge	Dakota	08-10	7001/HP	7020K	9154	9066K	56029319AC	9066K	D0203	MRXC4N3MF9
Dodge	Dakota	11	7001-R/ HP-R	VS80	9308	VS950	56029479AB	VS950	D0203	MRXC4N3MF9
Dodge	Dart	13-14			5775	VS90	68193586AC	VS90		KR55WY9012
Dodge	Durango	07-09	7001/HP	7020K	1051 **	1050K or 9066K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Dodge	Durango(433 Mhz)	11-14			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Dodge	Grand Caravan	02-03	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
Dodge	Grand Caravan	04-05	7001/HP	7020K	1052	1050K	04727392AB	NO	D0203	KR5S120123
Dodge	Grand Caravan	06-07	7001/HP	7020K	1051	1050K	56053030AB	NO	D0203	KR5S180052015B
Dodge	Grand Caravan	08-10	7004	7020K	1043	1050K	68001698AB	NO	D0203	KR5S180052020A
Dodge	Grand Caravan	10	7004	7020K	1043	7000K	68078768AA	VS70	D0203	KR5S180052020A
Dodge	Grand Caravan	11-14			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Dodge	Intrepid(433 Mhz)	02-04	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
Dodge	Journey(433 Mhz)	09-10	7004	7020K	1043	1050K	68001698AB	NO	D0203	KR5S180052020A
Dodge	Journey(433 Mhz)	10-14			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Dodge	Magnum	05-07	7001/HP	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Dodge	Magnum	08	7004	7020K	1043	1050K	68001698AB	NO	D0203	KR5S180052020A
Dodge	Nitro	07-09	7001/HP	7020K	1051 **	1050K or 9066K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Dodge	Nitro (433 Mhz)	07-09	7004	7020K	1043	1050K	68001698AB	NO	D0203	KR5S180052020A
Dodge	Nitro (433 Mhz)	10-11			9481	VS950	56029481AB	VS950	D0203	MRXC4N4MF9
Dodge	Ram Promaster	14			NEW		5154876AA			
Dodge	Ram(HP-315 Mhz) 1500	08			9154	9066K	56029319AC (Check VIN)	9066K	D0203	MRXC4N3MF9
Dodge	Ram(HP-315 Mhz) 2500	08-09	7001HP	7020K	9154	9066K	56029319AC (Check VIN)	9066K	D0203	MRXC4N3MF9
Dodge	Ram(433 Mhz) 1500	09	7004	7020K	1043	1050K	56029359AC	NO	D0203	KR5S180052020A
Dodge	Ram(433 Mhz) 1500/2500/3500	10-13			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Dodge	Ram(433 Mhz) 1500/2500	13-14			6815	NEW	68157568AB	NEW		GQ4-61T
Dodge	Stratus	07	7001/HP	7020K	1051	1050K	56053030AB	NO	D0203	KR5S180052015B
Dodge	Viper(433 Mhz)	03-07	7004	7020K	9028	1080K	52088990AD	NO		MRXTG224AM02
Dodge	Viper	08-14			9214	9066K	56029400AE	9066K	D0203	MRXMERCCTX1
**The 1050K is to be used on the Siemens sensors and the 2030K is to be used on the Schrader sensors.										
Ferrari	F430/Spider (433 Mhz)	06-07			9001	1090K	22 45 49	1092		OYGTSSRE4B
Ferrari	F430/Spider (433 Mhz) (Post July 2007)	08-10			9007 or 9011	1090K	23 92 98	1092		OYG TSSRE4TB
Ferrari	458 (433 Mhz)	10-14			9011	1096	23 92 98	1096		OYG TSSRE4TD
Ferrari	550 (433 Mhz)	02-14			9001	1090K	22 45 49	1092		OYGTSSRE4B
Ferrari	575M (433 Mhz)	02-06			9001	1090K	22 45 49	1092		OYGTSSRE4B
Ferrari	575 (315 Mhz)	02-05			9004	1090K	22 45 48	1092		OYGTSSRE3B
Ferrari	599 (433 Mhz)	04-14			9001	1090K	22 45 49	1092		OYGTSSRE4B
Ferrari	612 Scaglietta (433 Mhz)	04-12			9001	1090K	22 45 49	1092		OYGTSSRE4B
Ferrari	California (433 Mhz)	09-10			9008 or 9011	1090K	22 88 87	1092		OYG TSSRE4TC
Ferrari	California (433 Mhz)	11-14			9011	1096	23 92 98	1096		OYG TSSRE4TD

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Ferrari	Enzo (433 Mhz)	03-04			9005	1090K	22 45 51	1092		OYGTSSRE4PB
Ferrari	F12berlinetta (433 Mhz)	13-14			9011	1096	23 92 98	1096		OYG TSSRE4TD
Ferrari	FF (433 Mhz)	12-14			9011	1096	23 92 98	1096		OYG TSSRE4TD
Ferrari	FXX (433 Mhz)	05-06			9005	1090K	22 45 51	1092		OYGTSSRE4PB
Fiat	500(433 Mhz)	11-14			9398	VS950	56029398AB	VS950		MRXC4W4MA4
Ford	Crown Victoria	06-11	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	C-Max	12-14	7001-R/HP-R	VS80	9315	VS950	DE8T-1A180-AA	VS950	D0105	MRXFE3MAF4
Ford	E Series	07-09	7001HP-R	VS80	1048-HP	NA	8C2Z-1A189A	NO	D0101	KOBFTD06A
Ford	E Series(HP)	10-14	7001HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0101	MRXFE3MAF4
Ford	Edge	07-10	7001-R/HP-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Ford	Edge	11-14	7001-R/HP-R	VS80	9315	VS950	DE8T-1A180-AA	VS950	D0105	MRXFE3MAF4
Ford	Escape	06-08	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Escape	09-14	7001-R/HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0105	MRXFE3MAF4
Ford	Expedition	03-04	7004	7020K	9096	1060K	4L2T1A150BA	NO	D0104	MRXTG224AM02
Ford	Expedition	05-06	7001/HP	7020K	9135	1060K	5L1ZA150AB	NO	D0104	MRXTG224AM01
Ford	Expedition	07-10	7001-R/HP-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Ford	Expedition	11-14	7001-R/HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0105	MRXFE3MAF4
Ford	Explorer	02-05	7004	7020K	9096	1060K	4L2T1A150BA	NO	D0104	MRXTG224AM02
Ford	Explorer	06-10	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Explorer	11-14	7001-R/HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0105	MRXFE3MAF4
Ford	Explorer Sport Trac	07-10	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	F-150	07-08	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	F-150	09-14	7001-R/HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0105	MRXFE3MAF4
Ford	Fiesta	11-14	7001-R/HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0105	MRXFE3MAF4
Ford	500	08-09	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Flex	09-10	7001-R/HP-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Ford	Flex	11-14	7001-R/HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0105	MRXFE3MAF4
Ford	Focus	07-09	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A/ 7L1Z-1A189A	NO	D0105	KR5SWY7635
Ford	Focus	10-14	7001-R/HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0105	MRXFE3MAF4
Ford	Freestar	04-05	7001/HP	7020K	9135	1060K	5L1ZA150AB	NO	D0104	MRXTG224AM01
Ford	Freestar	06-07	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Fusion	07-09	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Fusion	10-14	7001-R/HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0105	MRXFE3MAF4
Ford	Mustang	07-09	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Mustang	10-14	7001-R/HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0105	MRXFE3MAF4
Ford	Mustang	14	7004	7020K	NEW	VS950	BB5Z-1A189A			
Ford	Ranger	07-11	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Ranger	12	7001-R/HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0105	MRXFE3MAF4
Ford	Shelby GT(>April 2012)	13	7001-R/HP-R	VS80	9315	VS925C	DR3Z-1A189A	VS925C		UNKNOWN

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Ford	Super Duty Pre-June 2009	07-10	7001HP-R	VS80	1048-HP	NA	8C2Z-1A189A	NO	D0101	KOBFTD06A
Ford	Super Duty Post-June 2009	10-14	7001HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0101	MRXFE3MAF4
Ford	Taurus (Pre-May 2010)	08-10	7001-R/ HP-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Ford	Taurus (Post-May 2010)	11-14	7001-R/ HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0105	MRXFE3MAF4
Ford	Taurus X	08-09	7001-R/ HP-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Ford	Transit	10-14	7001-R/ HP-R	VS80	9315	VS950	9L3Z-1A-189A	VS950	D0105	MRXFE3MAF4
*Redi-Sensor relearn must be performed with scan tool and not magnet.										
GMC	Acadia	07-08	7001/HP	7020K	NA	1050K	15921013	NO	D0305	MRXGMX272RS
GMC	Acadia	09-14	7001-R/ HP-R	VS80	9153	VS950	20923680	VS950	D0319	MRXG53MA4S
GMC	Canyon	07-12	7003	7020K	9131	1110K	15122618	NO	D0321	MRXGMT102PWM
GMC	Envoy	05-07	7001/HP	7020K	9116	1070K	25774006	NO	D0321	MRXGMT51MAN
GMC	Envoy	07-09	7001-R/ HP-R	VS80	9153	VS950	25920615	VS950	D0321	MRXG53MA4S
GMC	Savana	08-09	7001/HP	7020K	NA	1050K	15921013	NO	D0319	MRXGMX272RS
GMC	Savana	10-14	7001-R/ HP-R	VS80	9153	VS950	20923680	VS950	D0319	MRXG53MA4S
GMC	Sierra--All	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
GMC	Sierra--All	05-06	7003	7020K	9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
GMC	Sierra--1500	07	7001/HP	7020K	NA	2020K	15825475	NO	D0321	GQ428T
GMC	Sierra--1500	07	7001/HP	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
GMC	Sierra--1500	07-14	7001-R/ HP-R	VS80	9153	VS950	13589255	VS950	D0321	MRXG53MA4S
GMC	Sierra--2500/3500	07	7001HP	7020K	NA	2020K	15825475	NO	D0321	GQ428T
GMC	Sierra--2500/3500	07	7001HP	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
GMC	Sierra--2500/3500	07-15	7001HP-R	VS80	9153	VS950	13589255	VS950	D0321	MRXG53MA4S
GMC	Terrain	10-14	7001-R/ HP-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
GMC	Yukon--All	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
GMC	Yukon--All	05-06	7003	7020K	9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
GMC	Yukon	07	7001/HP	7020K	NA	2020K	15825475	NO	D0321	GQ428T
GMC	Yukon	07	7001/HP	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
GMC	Yukon	07-15	7001-R/ HP-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
GMC	Yukon--2500	07	7001HP	7020K	NA	2020K	15825475	NO	D0321	GQ428T
GMC	Yukon--2500	07	7001HP	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
GMC	Yukon--2500	07-13	7001HP-R	VS80	9153	VS950	13589255	VS950	D0321	MRXG53MA4S
Honda	Accord	08-12	7002	7020K	1208	1100K	42753-SWA-315/316	NO	A0201	PAXPMV107M
Honda	Civic	08-11	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	Civic	12-13	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	CR-V	07-11	7002	7020K	1208	1100K	42753-SWA-315/316	NO	A0201	PAXPMV107M
Honda	CR-V	12-13	7002	7020K	5511	7020K	42753-TP6-A82	VS70	A0201	KR5S180052015B
Honda	CR-Z	11-12	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	Crosstour	10-14	7002	7020K	5511	7020K	42753-TP6-A82	VS70	A0201	KR5S180052015B
Honda	Element	06-07	7002	7020K	1058	2000K	06421-SCV-A01	1096	A0201	T7B-2T
Honda	Element	08	7002	7020K	1058	2045K	42753-SHJ-A82	NO	A0201	GQ4-34T
Honda	Element	09-11	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	Fit	08	7002	7020K	1208	1100K	42753-SWA-315/316	NO	A0201	PAXPMV107M
Honda	Fit	09-13	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	Insight	10-13	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	Odyssey EX, EX-L, LX	06-07	7002	7020K	1058	2000K	06421-SCV-A00	1096	A0201	T7B-2T
Honda	Odyssey EX, EX-L, LX	08-10	7002	7020K	1058	2045K	42753-SHJ-A82	NO	A0201	GQ4-35T
Honda	Odyssey Touring	05-07			1057	2000K	06421-S3V-A04	1096	A0201	T7B-2T
Honda	Odyssey Touring	08-10			1057	2045	42753-SHJ-A53	NO	A0201	GQ4-35T
Honda	Odyssey and Touring	11-14	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	Pilot (Steel Wheels)	05			1059	2000K	06421-S9V-A02	1097	A0201	T7B-2T
Honda	Pilot (Alloy Wheels)	05-08			1057	2000K	06421-S3V-A04	1096	A0201	T7B-2T
Honda	Pilot (Alloy Wheels)	09-14			1209	1100K	42753-STK-A04	NO	A0201	PAXPMV107G
Honda	Pilot (Steel Wheels)	09-14			1219	1100K	42753-SZA-A13	NO	A0201	PAXPMV108G
Honda	Ridgeline (Steel Wheels)	06-08			1059	2000K	06421-S9V-A02	1097	A0201	T7B-2T
Honda	Ridgeline (Alloy Wheels)	06-08			1057	2000K	06421-S3V-A04	1096	A0201	T7B-2T

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Honda	Ridgeline (Alloy Wheels)	09-14			1057	2045K	42753-SHJ-A53	NO	A0201	GQ4-35T
Honda	S2000	08-09	7002	7020K	1208	1100K	42753-S2A-315	NO	A0201	PAXPMV107M
Hummer	H2	08-09	7001-R/HP-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Hummer	H3	06-10	7003	7020K	9131	1110K	15122618	NO	D0321	MRXGMT102PWW
Hummer	H3T	09-10	7003	7020K	9131	1110K	15122618	NO	D0321	MRXGMT102PWW
Hyundai	Accent(Lo-Line)	08-11	7002 or 1206A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0301	T7B-1T
Hyundai	Accent	12-13	7001/HP	7020K	5507	7020K	52933-2M000	VS70	A0301	KR5S180052015B
Hyundai	Accent	14	7001/HP	7020K	5507	7020K	52933-2M550	VS70	A0301	KR5S180052041
Hyundai	Azera	06-12	7002	7020K	1068	2000K	52933-2G200	1096	A0301	KOBHT05TPM
Hyundai	Azera	13-14			9505	VS950	52933-2V000	VS950	A0301	MRXFS5MAF4
Hyundai	Elantra	07-10	7002	7020K	1068	2000K	52933-2G200	1096	A0301	KOBHT05TPM
Hyundai	Elantra	11-14	7002	7020K	NEW	VS965	52933-3X200	VS965	A0301	GQ4-44T
Hyundai	Elantra(Touring)	09-12	7001/HP	7020K	5507	1050K or 7020K	52933-2L700	VS70	A0301	KR5S180052015B
Hyundai	Elantra GT	13	7001/HP	7020K	5507	7020K	52933-A5000	VS70	A0301	KR5S180052041
Hyundai	Entourage	07-09			1028	2000K	52933-4D200	1096	A0301	KOBHT05ATPM
Hyundai	Equus(Hi-Line)	11-13			1029	2040K	52933-2F000	NO	A0301	T7B-1T
Hyundai	Equus(Hi-Line)	14	7001/HP	7020K	5507	7020K	52933-A5000	VS70	A0301	KR5S180052041
Hyundai	Genesis(Hi-line)	09-14			1029	2040K	52933-2F000	NO	A0301	T7B-1T
Hyundai	Genesis Coupe	10-14	7001/HP	7020K	5507	7020K	52933-2M550	VS70	A0301	KR5S180052015B
Hyundai	Santa Fe (Thru July 2007)	07-08			1028	2000K	52933-4D200	1096	A0301	KOBHT05ATPM
Hyundai	Santa Fe (Thru Sept 2009)	08-10	7002	7020K	1068	2000K	52933-2G200	1096	A0301	KOBHT05TPM
Hyundai	Santa Fe (Post Oct 2009)	10-12	7002	7020K	1068	VS1010	52933-0W100	VS1010	A0301	UNKNOWN
Hyundai	Santa Fe	13-14	7001/HP	7020K	5507	7020K	52933-A5000	VS70	A0301	KR5S180052041
Hyundai	Sonata	07-08			1058	2000K	52933-3E000	1096	A0301	T7B-2T
Hyundai	Sonata(Lo-Line) Late '08 to'10	08-10	7002 or 1206A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0301	T7B-1T
Hyundai	Sonata	11-14	7001/HP	7020K	5507	7020K	52933-A5000	VS70	A0301	KR5S180052015B
Hyundai	Tiburon	07-08			1058	2000K	52933-3E000	1096	A0301	T7B-2T
Hyundai	Tucson	06-07			1058	2000K	52933-3E000	1096	A0301	T7B-2T
Hyundai	Tucson	08-10	7002	7020K	1058	2000K	52933-3E000	1096	A0301	T7B-2T
Hyundai	Tucson	10-13	7002 or 1206A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0301	T7B-1T
Hyundai	Tucson	14	7002	7020K	NEW	VS965	52933-2S500	VS965	A0301	GQ4-56T
Hyundai	Veloster	12-14			9505	VS950	52933-2V000	VS950	A0301	MRXFS5MAF4
Hyundai	Veracruz	07-08			1028	2000K	52933-4D200	1096	A0301	KOBHT05ATPM
Hyundai	Veracruz	08-12	7002	7020K	1068	2000K	52933-2G200	1096	A0301	KOBHT05TPM
**	Note: Use "TRW LoLine Fxd Dly" function on BarTec 400 or 400P to program the sensors.									
Infiniti	EX35	08-10	7001/HP	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Infiniti	EX35	11-12	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	EX37	13	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	FX35	03-08	7001/HP	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Infiniti	FX35(Post-June 2008)	09-10	7001/HP	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Infiniti	FX35	11-12	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	FX37	13	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	FX45(Pre-June 2007)	03-07	7001/HP	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Infiniti	FX45(Post-June 2007)	07-08	7001/HP	7020K	9204	2030K	40700-JA00C	NO	A0801	KOBHT05ATPM
Infiniti	FX50	09-10	7001/HP	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Infiniti	FX50	11-13	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	G25	11-12	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	G35	03-06	7001/HP	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Infiniti	G35(Sedan)	07-08	7001/HP	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Infiniti	G35(Coupe)	08	7001/HP	7020K	9204	2030K	40700-1AA0C	NO	A0801	KOBHT05ATPM
Infiniti	G37	08-10	7001/HP	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Infiniti	G37	11-13	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	JX35-433 Mhz	13			5556	7020K	40700-3JA0A	VS70	A0801	KR5S18052020A
Infiniti	M35	06-07	7001/HP	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Infiniti	M35	08-10	7001/HP	7020K	9204	2030K	40700-1AA0C	NO	A0801	KOBHT05ATPM
Infiniti	M35h	13	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	M37	11-13	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	M45	03-07	7001/HP	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Infiniti	M45	08-10	7001/HP	7020K	9204	2030K	40700-1AA0C	NO	A0801	KOBHT05ATPM
Infiniti	M56	11-13	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	Q45(pre-July 2006)	03-06	7001/HP	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Infiniti	Q45(Post-Aug 2006)	06	7001/HP	7020K	9204	2030K	40700-JA01B	NO	A0801	KOBHT05ATPM
Infiniti	QX4	03	7001/HP	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Infiniti	Q50	14			NEW	7020K	40700-4GA0A	VS70		
Infiniti	QX56(Steel)	05-06	7001/HP	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Infiniti	QX56(Alloy)	04-07	7001/HP	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Infiniti	QX56(Post-April 2007)	07-10	7001/HP	7020K	9204	2030K	40700-JA00C	NO	A0801	KOBHT05ATPM
Infiniti	QX56	11-13	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	Q60	14	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	QX50	14	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	QX60(433 MHz)	14			5556	7020K	40700-3JA0A	VS70	A0801	KR5S18052020A
Infiniti	QX70	14	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Infiniti	QX80	14	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
ITEC	Trucks(433 Mhz)	---			9010	VS9013 or VS9980	---	VS9013 or VS9980	---	OYGTSSRE4NB
Isuzu	Ascender	06-08	7001/HP	7020K	9116	1070K	25774006	NO	A0401	MRXGMT51MAN
Isuzu	I-290	07-08	7003	7020K	9131	1110K	15122618	NO	A0401	MRXGMT102PWW
Isuzu	I-370	07-08	7003	7020K	9131	1110K	15122618	NO	A0401	MRXGMT102PWW
Isuzu	Rodeo(433 Mhz)	04	7004	7020K	9028	1080K	52088990AC	NO	A0401	MRXTG224AM02
Jaguar	F(315 Mhz)	14			1045	7020K	CSD21601	VS70	E0401	KR5S180052015B
Jaguar	F(433 Mhz)	14			1046	7020K	C2D21599	VS70	E0401	NONE
Jaguar	Super V8(315 Mhz)	05-09		7020K	1055	1050K	C2Z15017	NO	E0401	KR5S120123
Jaguar	Super V8(433 mhz)	05-09		7020K	1046	1050K	C2Z15016	NO	E0401	NONE
Jaguar	Vanden Plas(315 Mhz)	04-09		7020K	1055	1050K	C2Z15017	NO	E0401	KR5S120123
Jaguar	Vanden Plas(433 Mhz)	04-09		7020K	1046	1050K	C2Z15016	NO	E0401	NONE
Jaguar	X Type(315 Mhz)	08		7020K	1055	1050K	C2Z15017	NO	E0401	KR5S120123
Jaguar	X Type(433 Mhz)	08		7020K	1046	1050K	C2Z15016	NO	E0401	NONE
Jaguar	XF(315 Mhz)	09-10		7020K	1055	1050K	C2Z15017	NO	E0401	KR5S120123
Jaguar	XF(315 Mhz)	11-14		7020K	1055	7020K	C2C41656	VS70	E0401	KR5S120123
Jaguar	XF(433 Mhz)	09-10		7020K	1046	1050K	C2Z15016	NO	E0401	NONE
Jaguar	XF(433 Mhz)	11-14		7020K	1046	7020K	C2C41655	NO	E0401	NONE
Jaguar	XJ(315 Mhz)	04-09		7020K	1055	1050K	C2Z15017	NO	E0401	KR5S120123
Jaguar	XJ(315 Mhz)	10-11		7020K	1055	7020K	C2Z15017	VS70	E0401	KR5S120123
Jaguar	XJ(315 Mhz)	12-14		7020K	1045	7020K	C2D21601	NO	E0401	KR5S180052015B
Jaguar	XJ(433 Mhz)	04-09		7020K	1046	1050K	C2Z15016	NO	E0401	NONE
Jaguar	XJ(433 Mhz)	10-13		7020K	1046	7020K	C2D21599	NO	E0401	NONE
Jaguar	XK(315 Mhz)	05-10		7020K	1055	1050K	C2Z15017	NO	E0401	KR5S120123
Jaguar	XK(315 Mhz)	10-14		7020K	1055	7020K	C2C41656	VS70	E0401	KR5S120123
Jaguar	XK(433 Mhz)	05-10		7020K	1046	1050K	C2Z15016	NO	E0401	NONE
Jaguar	XK(433 Mhz)	10-14		7020K	1046	7020K	C2C41655	NO	E0401	NONE
Jeep	Cherokee	14			6815	NEW	68157568AB	NEW		6Q4-61T
Jeep	Commander	06	7001/HP	7020K	1051	1050K	56029465AB	NO	D0203	KR5S180052015B
Jeep	Commander	07	7001/HP	7020K	**	1050K or 9066K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Commander	07-10	7004	7020K	**	1050K or 9066K	56029359AB	9066K	D0203	KR5S180052020 OR MRXDCA433TX1
Jeep	Compass	07-09	7001/HP	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Jeep	Compass	10	7001/HP	7020K	**	1050K or 9066K	68078861AA	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Compass	11-12	7001/HP	7020K	**	7000K or 9066K	68078861AA	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Compass	13-14	7001-R/HP-R	VS80	9308	VS950	56029479AB	VS950	D0203	MRXC4N3MF9

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Jeep	Compass	13-14			9481	VS950	56029481AB	VS950	D0203	MRXC4N4MF9
Jeep	Grand Cherokee	02-04	7004	7020K	9028	1080K	52088990AC	NO	D0202	MRXTG224AM02
Jeep	Grand Cherokee	05-06	7001/HP	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Jeep	Grand Cherokee	07	7001/HP	7020K	1051	1050K or 9066K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Grand Cherokee	08-10	7004	7020K	1043 **	1050K or 9066K	56029359AB	9066K	D0203	KR5S180052020 OR MRXDCA433TX1
Jeep	Grand Cherokee	11-14			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Jeep	Grand Cherokee SRT	12-14			9214	9066K	56029400AE	9066K	D0203	MRXMERCXTX1
Jeep	Liberty	02-04	7004	7020K	9028	1080K	52088990AC	NO	D0203	MRXTG224AM02
Jeep	Liberty	05-07	7001/HP	7020K	1051	1050K	56029465AB	NO	D0203	KR5S180052015B
Jeep	Liberty	08-10	7001/HP	7020K	1051 **	1050K or 9066K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Liberty	11-12	7001-R/HP-R	VS80	9308	VS950	56029479AB	VS950	D0203	MRXC4N3MF9
Jeep	Liberty (433 Mhz)	07-09	7004	7020K	1043 **	1050K or 9066K	56029359AB	9066K	D0203	KR5S180052020 OR MRXDCA433TX1
Jeep	Liberty (433 Mhz)	10-12			9481	VS950	56029481AB	VS950	D0203	MRXC4N4MF9
Jeep	Patriot	07-09	7001/HP	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Jeep	Patriot	10-12	7001/HP	7020K	1051 **	1050K or 9066K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Patriot	13-14	7001-R/HP-R	VS80	9308	VS950	56029479AB	VS950	D0203	MRXC4N3MF9
Jeep	Patriot (433 Mhz)	12-14			9481	VS950	56029481AB	VS950	D0203	MRXC4N4MF9
Jeep	Wrangler	07-10	7001/HP	7020K	1051 **	1050K or 9066K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Wrangler (433 Mhz)	08-10	7004	7020K	1043 **	1050K or 9066K	56029359AB	9066K	D0203	KR5S180052020 OR MRXDCA433TX1
Jeep	Wrangler	10-12	7001-R/HP-R	VS80	9308	VS950	56029479AB	VS950	D0203	MRXC4N3MF9
Jeep	Wrangler (433 Mhz)	13-14			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Jeep	Wrangler (433 Mhz)	11-12			9481	VS950	56029481AB	VS950	D0203	MRXC4N4MF9
**The 1050K is to be used on the Siemens sensors and the 2030K is to be used on the Schrader sensors.										
KIA	Amanti	07-08			1058	2000K	52933-3E000	1096	A0201	T7B-2T
KIA	Amanti	09	7002	7020K	1058	2000K	52933-3E000	1096	A0201	T7B-2T
KIA	Borrego(Lo-Line)	09	7002 or 1206A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0201	T7B-1T
KIA	Cadenza	14	7001/HP	7020K	5507	7020K	52933-A5000	VS70	A0201	KR5S180052041
KIA	Forte	10-13	7001/HP	7020K	5507	7020K	52933-2M000	VS70	A0201	KR5S180052015B
KIA	Forte	14			NEW	VS965	52933-A7000	VS965		GQ4-64T
KIA	Magentis	08-10	7002	7020K	1068	2000K	52933-2G200	1096	A0201	KOBHT05TPM
KIA	Mohave	09	7002 or 1206A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0201	T7B-1T
KIA	Optima(Lo-Line)	06-10	7002	7020K	1068	2000K	52933-2G200	1096	A0201	KOBHT05TPM
KIA	Optima	11-14	7001/HP	7020K	5507	7020K	52933-2M000/52933-2M550	VS70	A0201	KR5S180052015B/ KR5S180052041
KIA	Rio5(Lo-Line)	08-11	7002 or 1206A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0201	T7B-1T
KIA	Rio5(Lo-Line)	12-14	7002	7020K	NEW	VS965	52933-3X200	VS965	A0201	GQ4-44T
KIA	Rondo(Lo-Line)	07-09	7002	7020K	1068	2000K	52933-2G200	1096	A0201	KOBHT05TPM
KIA	Sedona(Hi-Line)	06-08			1028	2000K	52933-4D200	1096	A0201	KOBHT05ATPM
KIA	Sedona(Lo-Line)	09-14	7002	7020K	1068	2000K	52933-2G200	1096	A0201	KOBHT05TPM

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
KIA	Sorento	05-07			1058	2000K	52933-3E000	1096	A0201	T7B-2T
KIA	Sorento	08-09	7002	7020K	1058	2000K	52933-3E000	1096	A0201	T7B-2T
KIA	Sorento	11-14	7001/HP	7020K	5507	7020K	52933-2M000	VS70	A0201	KR5S180052015B
KIA	Soul	10-13	7001/HP	7020K	5507	7020K	52933-2M000	VS70	A0201	KR5S180052015B
KIA	Soul (433 Mhz)	14			NEW		52933-B2100			MRXHH4
KIA	Spectra-5(Lo-Line)	07-09	7002 or 1206A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0201	T7B-1T
KIA	Sportage	06-07			1058	2000K	52933-3E000	1096	A0201	T7B-2T
KIA	Sportage	08	7002	7020K	1058	2000K	52933-3E000	1096	A0201	T7B-2T
KIA	Sportage(Lo-Line)	09-13	7002 or 1206A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0201	T7B-1T
KIA	Sportage	14			NEW	VS965	52933-2S500	VS965	A0201	GQ4-56T
KIA	Tuscany	07-08			1058	2000K	Enhanced/Basic	1096	A0201	T7B-2T
**	Note: Use "TRW LoLine Fxd Dly" function on BarTec 400 or 400P to program the sensors.									
Land Rover	LR2(315 Mhz)	08-10			1045	1050K	LR032833	NO	E0401	KR5S180052015B
Land Rover	LR2(315 Mhz)	10-14			1045	7020K	LR032833	VS70	E0401	KR5S180052015B
Land Rover	LR2(433 Mhz)	10-12			1046	7020K	LR018861	VS70	E0401	NONE
Land Rover	LR3(433 Mhz)	02-05			9003	1090K	YDB 0000 60	1092-1095	E0401	OYG TSSRE4PB
Land Rover	LR3(315 Mhz)	06-09			1055	1050K	LR018860	NO	E0401	KR5S120123
Land Rover	LR3(433 Mhz)	06-09			1046	1050K	LR018861	NO	E0401	NONE
Land Rover	LR4(315 Mhz)	10-13			1045*	7020K	LR032833	VS70	E0401	KR5S180052015B
Land Rover	LR4(433 Mhz)	10-14			1046*	7020K	LR018861	VS70	E0401	NONE
Land Rover	Evoque(315 Mhz)	11-14			1045	7020K	LR032833	NO	E0401	KR5S180052015B
Land Rover	Range Rover (315 Mhz)	06-09			1055	1050K	LR018860	NO	E0401	KR5S120123
Land Rover	Range Rover (315 Mhz)	10-14			1045*	7020K	LR032833	VS70	E0401	KR5S180052015B
Land Rover	Range Rover (433 Mhz)	06-09			1046	1050K	LR018861	NO	E0401	NONE
Land Rover	Range Rover (433 Mhz)	10-14			1046*	7020K	LR018861	VS70	E0401	NONE
Land Rover	Range Rover Sport (315 Mhz)	06-09			1055	1050K	LR021936	NO	E0401	KR5S120123
Land Rover	Range Rover Sport (315 Mhz)	10-14			1045*	7020K	LR032833	VS70	E0401	KR5S180052015B
Land Rover	Range Rover Sport (433 Mhz)	06-09			1046	1050K	LR018861	NO	E0401	NONE
Land Rover	Range Rover Sport (433 Mhz)	10-14			1046*	7020K	LR018861	VS70	E0401	NONE
NOTE: (*)Utilize the VIN on MY 2013 - 14 vehicles in detemining the correct sensor frequency.										
Lexus	CT	11-13	7002 or 1204A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lexus	ES	07-12	7002 or 1204A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lexus	ES	13-14	7003	7020K	1218	1100K	42607-30060	NO	A1101	PAXPMVC010
Lexus	GS	05-12	7002 or 1204A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lexus	GS	13-14	7003	7020K	1218	1100K	42607-30060	NO	A1101	PAXPMVC010
LexusTruck	GX470	04-06	7002 or 1204A	7020K	1204	1110K	42607-35010	NO	A1101	PAXPMV107J
Lexus Truck	GX	07-14	7002 or 1204A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lexus	HS Series	11-12	7002 or 1204A	7020K	1204	1100K	42607-75010	NO	A1101	PAXPMV107J

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Lexus	IS Series	06-14	7002 or 1204A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lexus	LFA	12	7002 or 1204A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lexus	LS	07-12	7002 or 1204A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lexus	LS	13-14	7003	7020K	1218	1100K	42607-30060	NO	A1101	PAXPMVC010
Lexus	LX	05-14	7002 or 1204A	7020K	1204	1100K	42607-33021	NO	A1201	PAXPMV107J
Lexus Truck	RX	06-14	7002 or 1204A	7020K	1204	1100K	42607-33021	NO	A1201	PAXPMV107J
Lexus	SC430	02-06			1217-WH 1217-BL 1217-RD 1217-YL	1120K	42607-24010 42607-24020 42607-24030 42607-24040	NO		PAXPMV1001
Lexus	SC	07-10	7002 or 1204A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lincoln	Aviator(433 Mhz)	03-05	*7004	7020K	9096	1060K	4L2T1A150-BA	NO	D0104	MRXTG224AM02
Lincoln	Mark LT	07-08	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Lincoln	MKS	09-10	7001-R/HP-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Lincoln	MKS	11-14	7001-R/HP-R	VS80	9315	VS950	CM5T-1A150AA	VS950	D0105	MRXFE3MAF4
Lincoln	MKT	10	7001-R/HP-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Lincoln	MKT	11-14	7001-R/HP-R	VS80	9315	VS950	CM5T-1A150AA	VS950	D0105	MRXFE3MAF4
Lincoln	MKT 433 Mhz	14	7004	7020K	NEW	VS950	BB5Z-1A189A	VS950		
Lincoln	MKX	07-10	7001-R/HP-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Lincoln	MKX	11-13	7001-R/HP-R	VS80	9315	VS950	9L3Z-1A189A	VS950	D0105	MRXFE3MAF4
Lincoln	MKZ	07-09	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Lincoln	MKZ	10-14	7001-R/HP-R	VS80	9315	VS950	CM5T-1A150AA	VS950	D0105	MRXFE3MAF4
Lincoln	Navigator	03-04	*7004	7020K	9096	1060K	4L2T1A150-BA	NO	D0104	MRXTG224AM02
Lincoln	Navigator	05-06	7001/HP	7020K	9135	1060K	5L1Z1A150-AB	NO	D0104	MRXTG224AM01
Lincoln	Navigator	07-10	7001-R/HP-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Lincoln	Navigator	11-14	7001-R/HP-R	VS80	9315	VS950	CM5T-1A150AA	VS950	D0105	MRXFE3MAF4
Lincoln	Town Car	06-11	7001-R/HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
*Redi-Sensor relearn must be performed with scan tool and not magnet.										
Maserati	Quattroporte-- Thru December 2009	04-09			9001	1090K	22 45 49	1092		OYGTSSRE4B
Maserati	Quattroporte-- Post January 2010	10-14			9011	1096	24 88 87	1096		OYG TSSRE4TD
Maserati	Coupe-- Thru June 2009	09			9001	1090K	22 45 49	1092		OYGTSSRE4B
Maserati	Coupe-- Post July 2009	09-14			9011	1096	24 88 87	1096		OYG TSSRE4TD
Mazda	B Series	07-09	7001/HP	7020K	1048	NA	6F2Z-1A189A	NO	A0602	KR5SWY7635
Mazda	2	11-14	7001/HP	7020K	1056	7020K	BHA4-37-140	VS70	A0601	KR5S180052015B
Mazda	3	04	7001/HP	7020K	1056	NA	FE01-37-140A/ GN3A-37-140B	NO	A0601	KR5S180052015B
Mazda	3	05-09	7001/HP	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	3	10-13	7001/HP	7020K	1056	7020K	BHA4-37-140	VS70	A0601	KR5S180052015B
Mazda	5	06-09	7001/HP	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Mazda	5	10-12	7001/HP	7020K	1056	7020K	BHA4-37-140	VS70	A0601	KR5S180052015B
Mazda	6	05-10	7001/HP	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	6	10-13	7001/HP	7020K	1056	7020K	BHA4-37-140	VS70	A0601	KR5S180052015B
Mazda	CX-7	07-09	7001/HP	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	CX-7	10-12	7001/HP	7020K	1056	7020K	BHA4-37-140	VS70	A0601	KR5S180052015B
Mazda	CX-9	07-09	7001/HP	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	CX-9	10-14	7001/HP	7020K	1056	7020K	BHA4-37-140	VS70	A0601	KR5S180052015B
Mazda	MX-5 Miata	06-09	7001/HP	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	MX-5 Miata	10-14	7001/HP	7020K	1056	7020K	BHA4-37-140	VS70	A0601	KR5S180052015B
Mazda	RX8	04	7001/HP	7020K	1056	NA	FE01-37-140A/ GN3A-37-140B	NO	A0601	KR5S180052015B
Mazda	RX8	05-09	7001/HP	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	RX8	10-11	7001/HP	7020K	1056	7020K	BHA4-37-140	VS70	A0601	KR5S180052015B
Mazda	Speed 3	10-12	7001/HP	7020K	1056	7020K	BHA4-37-140	VS70	A0601	KR5S180052015B
Mazda	Speed 6	07-08	7001/HP	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	Tribute	06-08	7001/HP	7020K	1048	NA	6F2Z-1A189A	NO	A0602	KR5SWY7635
Mazda	Tribute	09-11	7001-R/ HP-R	VS80	9315	VS950	9L3Z-1A189A	VS950	A0602	MRXFE3MAF4
M-Benz	C Class(433 Mhz)	07-14			9214	2030K	000 905 7200	9066K	E0703	MRXMW2433A
M-Benz	CLA	14			9214	2030K	000 905 7200	9066K	E0703	MRXMW2433A
M-Benz	CL Class(315 Mhz)	00-06			9004	1090K	000 822 34 06	1094	E0703	OYGTSSRE3B
M-Benz	CL Class(433 Mhz)	00-06			9001	1090K	000 822 3306	1094	E0703	OYGTSSRE4B
M-Benz	CL Class(433 Mhz)	09-14			9214	2030K	000 905 7200	9066K	E0703	MRXMW2433A
M-Benz	CL 63-65-550-600 (315 Mhz)	07-11	7003	7020K	1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	CL 63-65-550-600 (433 Mhz)	07-11			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	CLKClass(315 Mhz)	06-07			9004	1090K	000 822 34 06	1094	E0701	OYGTSSRE3B
M-Benz	CLK Class(433 Mhz)	08-09			9214	2030K	000 905 4100	9066K	E0703	MRXMW2433A
M-Benz	CLS 55-63-500-550 (315 Mhz)	06-11	7003	7020K	1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	CLS 55-63-500-550 (433 Mhz)	06-09			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	CLS Class(433 Mhz)	08-14			9214	2030K	000 905 4100	9066K	E0703	MRXMW2433A
M-Benz	CLS Class(433 Mhz)	11			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	E Class(315 Mhz)	00-05			9004	1090K	000 822 34 06	1094	E0703	OYGTSSRE3B
M-Benz	E Class(433 Mhz)	00-05			9001	1090K	000 822 33 06	1094	E0703	OYGTSSRE4B
M-Benz	E Class(315 Mhz)	06-10	7003	7020K	1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	E Class(433 Mhz)	06-10			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	E Class(433 Mhz)	10-14			9214	2030K	000 905 7200	9066K	E0703	MRXMW2433A
M-Benz	G Class(433 Mhz)	07-14			9214	2030K	000 905 4100	9066K	E0703	MRXMW2433A
M-Benz	GL Class(315 Mhz)	07-09	7003	7020K	1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	GL Class(433 Mhz)	07-09			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	GL(433 Mhz)	10-14			9214	2030K	000 905 7200	9066K	E0703	MRXMW2433A
M-Benz	GLK(433 Mhz)	10-14			9214	2030K	000 905 7200	9066K	E0703	MRXMW2433A
M-Benz	ML Class(315 Mhz)	06-10	7003	7020K	1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	ML Class(433 Mhz)	06-10			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	ML Class(433 Mhz)	10-14			9214	2030K	000 905 7200	9066K	E0703	MRXMW2433A
M-Benz	R Class(315 Mhz)	06-09	7003	7020K	1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	R Class(433 Mhz)	06-09			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	R Class(433 Mhz)	10			9214	2030K	000 905 4100	9066K	E0703	MRXMW2433A
M-Benz	R Class(433 Mhz)	11			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	R Class(433 Mhz)	12			9214	2030K	000 905 4100	9066K	E0703	MRXMW2433A
M-Benz	S Class(315 Mhz)	00-06			9004	1090K	000 822 34 06	1094	E0703	OYGTSSRE3B
M-Benz	S Class(433 Mhz)	00-06			9001	1090K	000 822 33 06	1094	E0703	OYGTSSRE4B

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
M-Benz	S Class(315 Mhz)	07-11	7003	7020K	1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	S Class(433 Mhz)	07-10			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	S(433 Mhz)	10-14			9214	2030K	000 905 4100	9066K	E0703	MRXMW2433A
M-Benz	SL Class(315 Mhz)	00-05			9004	1090K	000 822 34 06	1094	E0703	OYGTSSRE3B
M-Benz	SL Class(433 Mhz)	00-05			9001	1090K	000 822 33 06	1094	E0703	OYGTSSRE4B
M-Benz	SL Class(315 Mhz)	06-12	7003	7020K	1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	SL Class(433 Mhz)	06-09			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	SL Class(433 Mhz)	13-14			9214	2030K	000 905 7200	9066K	E0703	MRXMW2433A
M-Benz	SLK Class(433 Mhz)	08-14			9214	2030K	000 905 7200	9066K	E0703	MRXMW2433A
M-Benz	SLR Class(315 Mhz)	04-06			9004	1090K	000 822 34 06	1094	E0703	OYGTSSRE3B
M-Benz	SLR Class(433 Mhz)	00-06			9001	1090K	000 822 33 06	1094	E0703	OYGTSSRE4B
M-Benz	SLR Class(315 Mhz)	08-09	7003	7020K	1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	SLR Class(433 Mhz)	08-09			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	SLS(433 mhz)	11-14			9214	2030K	000 905 7200	9066K	E0703	MRXMW2433A
M-Benz	Sprinter	07-13			1042	1098K	68038945AA	1098K	D0203	KR5S122228001
M-Benz	Sprinter	14			9214	2030K	000 905 7200	9066K	E0703	MRXMW2433A
Mercury	Grand Marquis	07-10	7001-R/ HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Mercury	Mariner	06-08	7001-R/ HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Mercury	Mariner	09-11	7001-R/ HP-R	VS80	9315	VS950	9L3Z-1A189-A	VS950	D0105	MRXFE3MAF4
Mercury	Milan	08-09	7001-R/ HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Mercury	Milan	10-11	7001-R/ HP-R	VS80	9315	VS950	9L3Z-1A189-A	VS950	D0105	MRXFE3MAF4
Mercury	Montego	06-07	7001-R/ HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Mercury	Monterey	04-05	7001/HP	7020K	9135	1060K	5L1Z1A150-AB	NO	D0104	MRXTG224AM01
Mercury	Monterey	06-07	7001-R/ HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Mercury	Mountaineer	02-05	7004	7020K	9096	1060K	4L2T1A150-BA	NO	D0104	MRXTG224AM02
Mercury	Mountaineer	06-10	7001-R/ HP-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Mercury	Sable	08-09	7001-R/ HP-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
*Redi-Sensor relearn must be performed with scan tool and not magnet.										
Mini	All(433 Mhz)	07-09			1027	1090K	36 23 6 781 847	1094	E0802	OYGTSSRE4TC
Mini	All(433 Mhz) (September 2009)	10-14			9012	1096	36 10 6 856 227	1096	E0802	OYGTSSRE4DB
Mitsubishi	Eclipse(Alloy)	06-12	7001/HP	7020K	9034	1080K	425 0B 877	NO	A0701	MRX2T315AMA
Mitsubishi	Eclipse(Steel)	06-07	7001/HP	7020K	9069	1130K	4250A030	NO	A0701	MRXNG33MA4S
Mitsubishi	Endeavor(pre Sep '06)	04-06	7004	7020K	9028	1080K	MN103033	NO	A0701	MRXTG224AM02
Mitsubishi	Endeavor(post Sep '06)	06-12	7001/HP	7020K	9034	1080K	425 0B 877	NO	A0701	MRX2T315AMA
Mitsubishi	Galant	04-06	7004	7020K	9028	1080K	MN103033	NO	A0701	MRXTG224AM02
Mitsubishi	Galant (Alloy)	07-12	7001/HP	7020K	9034	1080K	425 0B 877	NO	A0701	MRX2T315AMA
Mitsubishi	Galant (Steel)	07-12	7001/HP	7020K	9069	1130K	425 0B 875	NO	A0701	MRXNG33MA4S
Mitsubishi	i-MiEV	12-13			**	7020K	425 0B 975	VS70	A0701	KR5S180052015B
Mitsubishi	Lancer**	08-10			**	1050K	425 0B 975	NO	A0701	KR5S180052015B
Mitsubishi	Lancer**	10-14			**	7020K	425 0B 975	VS70	A0701	KR5S180052015B
Mitsubishi	Mirage	14			NEW	VS90	425 0C 276	VS90	A0701	
Mitsubishi	Mirage (Post September '13)	14			**	7020K	425 0B 975	VS70	A0701	KR5S180052015B
Mitsubishi	Montero	03-05	7001/HP	7020K	9034	1080K	MN103081	NO	A0701	MRX2T315AMA
Mitsubishi	Outlander**	07-10			**	1050K	425 0B 975	NO	A0701	KR5S180052015B
Mitsubishi	Outlander**	10-14			**	7020K	425 0B 975	VS70	A0701	KR5S180052015B
Mitsubishi	Outlander Sport	14			**	7020K	425 0B 975	VS70	A0701	KR5S180052015B
Mitsubishi	Raider	08-09	7001/HP	7020K	9154	9066K	56029319AB	9066K	A0701	MRXC4N3MF9
**See dealer for replacement sensor and relearn										
Nissan	350Z	04-06	7001/HP	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Nissan	350Z	07-09	7001/HP	7020K	9204	2030K	40700-JA00C	NO	A0801	KOBHT05ATPM
Nissan	370Z	08-10	7001/HP	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Nissan	370Z	11-14	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Nissan	Altima	06-11	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Altima	12	7001/HP	7020K	5555	7020K	40700-3AN0A	VS70	A0801	KR5S180052033
Nissan	Altima (433 Mhz)	13-14			5556	7020K	40700-3JA0A	VS70	A0801	KR5S18052020A
Nissan	Altima Coupe	13	7001/HP	7020K	5555	7020K	40700-3AN0A	VS70	A0801	KR5S180052033
Nissan	Armada(Alloy)--SE	05-08	7001/HP	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Armada(Steel)	05-06	7001/HP	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Nissan	Armada-LE	09-14	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Cube (<11/11)	09-12	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Cube 1.8 & 1.8 S CVT (11/11-3/12)	12	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Cube-1.8 SL (10/10-11/11)	11-12			5557	7020K	40700-3AN1A	VS70	A0801	KR5S180020158
Nissan	Cube 1.8 & 1.8S (3/12-9/13)	12-13	7001/HP	7020K	9204	1100K	40700-JK01B	NO	A0801	KOBHT05ATPM
Nissan	Cube 1.8 S CVT (>11/11)	12-14	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Nissan	Frontier	03-04	7001/HP	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Nissan	Frontier(Alloy)	05-08	7001/HP	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Frontier(Steel)	05-07	7001/HP	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Nissan	Frontier (5/08 - 10/13)	09-13	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Frontier (1/12 - 10/13)	11-13	7001/HP	7020K	5555	7020K	40700-3AN0A	VS70	A0801	KR5S180052033
Nissan	GT-R	09-14	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Juke Base (Without I-Key <3/12)	11	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Juke Base (Without I-Key-- Post 3/12)	12-14	7001/HP	7020K	9204	1100K	40700-JK01B	NO	A0801	KOBHT05ATPM
Nissan	Juke SV & SL (With I-Key-- 7/10 - 7/11)	11	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Nissan	Juke (With I-Key-- 7/11 - 9/11)	11			5557	7020K	40700-3AN1A	VS70	A0801	KR5S180020158
Nissan	Juke (With I-Key-- Post 2/12)	12-14	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Nissan	Leaf	11-13	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Nissan	Leaf(> 12/12)	13-14			5557	7020K	40700-3AN1A	VS70	A0801	KR5S180020158
Nissan	Maxima	06-07	7001/HP	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Maxima	07-12	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Maxima	12-14	7001/HP	7020K	5555	7020K	4070-3AN0A	VS70		KR5S180052033
Nissan	Murano	03-06	7001/HP	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Nissan	Murano	07-12	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Murano(> 11/11)	12-14	7001/HP	7020K	9204	1100K	40700-JK01B	NO	A0801	KOBHT05ATPM
Nissan	NV200	13-14	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	NV 1500/2500HD/3500HD	12-14			NEW	2030K	40700-1PA0A			UNKNOWN
Nissan	Pathfinder	03-04	7001/HP	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Nissan	Pathfinder(Steel)	04	7001/HP	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Nissan	Pathfinder	05-06	7001/HP	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Pathfinder	07-12	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Pathfinder (433 Mhz)	13-14			5556	7020K	40700-3JA0A	VS70		KR5S18052020A
Nissan	Quest(Steel)	04-07	7001/HP	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Nissan	Quest(Alloy)	05-06	7001/HP	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Quest	07-09	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Quest	11-14	7003	7020K	1216	1100K	40700-1LA0E	NO	A0801	PAXPMV107S
Nissan	Rogue	08-11	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Rogue(> 11/11)	12-13	7001/HP	7020K	9204	1100K	40700-JK01B	NO	A0801	KOBHT05ATPM
Nissan	Rogue (433 Mhz)	14			NEW	7020K	40700-3VU0A	VS70	A0801	

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Nissan	Sentra(Alloy)	07-08	7001/HP	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Sentra	07-12	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Sentra(> 1/12)	12-13	7001/HP	7020K	9204	1100K	40700-JK01B	NO	A0801	KOBHT05ATPM
Nissan	Sentra(> 9/12) without I-KEY	13-14	7001/HP	7020K	5555	7020K	40700-3AN0A	VS70	A0801	KR5S180052033
Nissan	Sentra(> 12/12) with I-KEY	13-14			5557	7020K	40700-3AN1A	VS70	A0801	KR5S180020158
Nissan	Titan(Alloy)	05-07	7001/HP	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Titan(Steel)	04-05	7001/HP	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Nissan	Titan (Post April)	07-14	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Versa (Dec 2011)	07-11	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Versa Sedan	12	7001/HP	7020K	5555	7020K	40700-3AN0A	VS70	A0801	KR5S180052033
Nissan	Versa Sedan--Low/Base	13-14	7001/HP	7020K	5555	7020K	40700-3AN0A	VS70	A0801	KR5S180052033
Nissan	Versa Sedan--Mid	13-14			5557	7020K	40700-3AN1A	VS70	A0801	KR5S180020158
Nissan	Versa Hatchback (Post -- Jan 2012)	12	7001/HP	7020K	9204	1100K	40700-JK01B	NO	A0801	KOBHT05ATPM
Nissan	Versa Note--S & SV	14	7001/HP	7020K	5555	7020K	40700-3AN0A	VS70	A0801	KR5S180052033
Nissan	Versa Note--SL	14			5557	7020K	40700-3AN1A	VS70	A0801	KR5S180020158
Nissan	Xterra	03-04	7001/HP	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Nissan	Xterra	05-06	7001/HP	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Xterra(Steel)	06-07	7001/HP	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Nissan	Xterra <10/13)	07-12	7001/HP	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Xterra Pro-S-4X (12/12 - 10/13)	13	7001/HP	7020K	5555	7020K	40700-3AN0A	VS70	A0801	KR5S180052033
Pontiac	G3	09			9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Pontiac	G5	08	7001/HP	7020K	NA	1050K	15921013	NO	D0305	MRXGMX272RS
Pontiac	G5	09-10	7001-R/HP-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Pontiac	G6(Pre-10/15/07)	08	7001/HP	7020K	NA	1050K	15921013	NO	D0305	MRXGMX272RS
Pontiac	G6(Post-10/15/07)	08-10	7001-R/HP-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Pontiac	G8	08-09	7001-R/HP-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Pontiac	Grand Prix	07-08	7001/HP	7020K	NA	1050K	15921013	NO	D0305	MRXGMX272RS
Pontiac	Grand Prix	08	7001-R/HP-R	VS80	9153	VS950	259220615	VS950	D0305	MRXG53MA4S
Pontiac	Montana	08	7001/HP	7020K	9158	1070K	15268606	NO	D0305	MRXGMX272RS
Pontiac	Solstice	08-09	7001/HP	7020K	NA	1050K	15921013	NO	D0305	MRXGMX272RS
Pontiac	Torrent	07-09	7001/HP	7020K	NA	1050K	10394110	NO	D0305	MRXGMX272RS
Pontiac	Vibe	08-10	1204A	1100K	1204	1100K	88974915	NO	D0312	PAXPMV107J
Pontiac	Wave	08			9153	VS950	25920615	VS950	D0305	MRXG53MA4S
**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.										
Porsche	911 Carrera(433 Mhz)	05-08			9001	1090K	997 606 021 01	1092	E0901	OYGTSSRE4B
Porsche	911 Carrera(433 Mhz) (Post April 2008)	09-11			9008 or 9011	1090K	997 606 021 20	1092	E0901	OYG TSSRE4TC
Porsche	911 Carrera (433 Mhz)	12-14			9011	1096	958 361 661 00	1096	E0901	OYG TSSRE4TD
Porsche	911 Carrera(315 Mhz)	05-08			9004	1090K	997 606 023 21	1092	E0901	OYGTSSRE3B
Porsche	911 Turbo(433 Mhz)	07-09			9001	1090K	997 606 021 01	1092	E0901	OYGTSSRE4B
Porsche	911 Turbo(433 Mhz)	10-14			9011	1096	958 361 661 00	1096	E0901	OYG TSSRE4TD
Porsche	911 Turbo(315 Mhz)	07-09			9004	1090K	997 606 023 21	1092	E0901	OYGTSSRE3B
Porsche	911 Turbo(315 Mhz)	10-14			NEW					
Porsche	Boxster(433 Mhz)	05-08			9001	1090K	997 606 021 01	1092	E0901	OYGTSSRE4B
Porsche	Boxster(433 Mhz)-(Thru July 2011)	09-11			9008 or 9011	1090K	997 606 021 20	1092	E0901	OYG TSSRE4TC
Porsche	Boxster (433 Mhz)	12-14			9011	1096	958 361 661 00	1096	E0901	OYG TSSRE4TD
Porsche	Boxster(315 Mhz)	05-08			9004	1090K	997 606 023 21	1092	E0901	OYGTSSRE3B

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Porsche	Boxster(315 Mhz) Post November 2008)				NEW					
Porsche	Carrera GT(433 Mhz)	03-06			9001	1090K	997 606 021 01	1092	E0901	OYGTSSRE4B
Porsche	Carrera GT(315 Mhz)	04-06			9004	1090K	997 606 023 21	1092	E0901	OYGTSSRE3B
Porsche	Cayenne(433 Mhz)	03-06			9005	1090K	955 361 661 01	1092	E0901	OYGTSSRE4PB
Porsche	Cayenne(315 Mhz)	09-10			9004	1090K	955 606 023 01	1092	E0901	OYGTSSRE3B
Porsche	Cayenne(433 Mhz)	07-10			9007 or 9011	1090K	955 606 021 00	1092	E0901	OYG TSSRE4TB
Porsche	Cayenne (433 Mhz)	11-14			9011	1096	958 361 661 00	1096	E0901	OYG TSSRE4TD
Porsche	Cayman(433 Mhz)	05-08			9001	1090K	997 606 021 01	1092	E0901	OYGTSSRE4B
Porsche	Cayman(433 Mhz)	09-10			9008 or 9011	1090K	997 606 021 20	1092	E0902	OYG TSSRE4TC
Porsche	Cayman (433 Mhz)	11-14			9011	1096	958 361 661 00	1096	E0901	OYG TSSRE4TD
Porsche	Cayman(315 Mhz)	05-08			9004	1090K	997 606 023 21	1092	E0901	OYGTSSRE3B
Porsche	Cayman(315 Mhz)	09-14			NEW					
Porsche	997 GT3(433 Mhz)	07-09			9001	1090K	997 606 021 01	1092	E0901	OYGTSSRE4B
Porsche	997 GT3(433 Mhz)	10-14			9011	1096	958 361 661 00	1096	E0901	OYG TSSRE4TD
Porsche	997 GT3(315 Mhz)	07-09			9004	1090K	997 606 023 21	1092	E0901	OYGTSSRE3B
Porsche	997 GT3(315 Mhz)	10-14			NEW					
Porsche	Panamera(315 Mhz)	10-14			9004	1090K	997 606 023 21	1092	E0901	OYGTSSRE3B
Porsche	Panamera(433 Mhz)	10-11			9008 or 9011	1090K	997 606 021 20	1092	E0901	OYG TSSRE4TC
Porsche	Panamera (433 Mhz)	12-13			9011	1096	958 361 661 00	1096	E0901	OYG TSSRE4TD
Porsche	Panamera (433 Mhz)	14			9018	1096	5Q0 907 275	1096	E0901	
Rolls Royce	Phantom(433 Mhz)	07-11			1027	1090K	NA	1092 or 1094		OYGTSSRE4TC
Rolls Royce	Phantom(433 Mhz)	12-14			9012	1096	36 10 6 856 227	1096	E0201	OYGTSSRE4DB
Rolls Royce	Cabrio(433 Mhz)	10-12			1027	1090K	NA	1092 or 1094		OYGTSSRE4TC
Saab	9-3(433 Mhz)	04-07			9078	2010K	13172567	NO	E1001	MRXGME433TX2
Saab	9-3(433 Mhz)	08-12				2010K	13227143	NO	E1001	MRXGME433WAL
Saab	9-5(433 Mhz)	04-07			9078	2010K	13172567	NO	E1001	MRXGME433TX2
Saab	9-5(433 Mhz)	08-12				2010K	13227143	NO	E1001	MRXGME433WAL
Saab	9-7X(315 Mhz)	05-09	7001/HP	7020K	9116	1070K	25774006	NO	E1002	MRXGMT51MAN
Saturn	Astra(433 Mhz)	08-09			9078	2010K	13172567	NO	D0305	MRXGME433TX2
Saturn	Aura(<10/14/07)	07-08	7001/HP	7020K	NA	1050K	15921013	NO	D0305	MRXGMX272RS
Saturn	Aura(>10/14/07)	08-09	7001-R/ HP-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Saturn	Lamda Crossover	07-08	7001/HP	7020K	9158	1070K	15268606	NO	D0305	MRXGMX272RS
Saturn	Outlook	07-08	7001/HP	7020K	NA	1050K	15921013	NO	D0305	MRXGMX272RS
Saturn	Outlook	09-10	7001-R/ HP-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Saturn	Sky	08-09	7001/HP	7020K	NA	1050K	15921013	NO	D0305	MRXGMX272RS
Saturn	Vue	07-10	7001-R/ HP-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.										
Scion	tC	06-14	7002 or 1204A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Scion	FR-S	13-14	7003	7020K	1218	1100K	SU003-00754	NO	A1101	PAXPMVC010
Scion	iQ	12-14	7002 or 1204A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Scion	xB	08-14	7002 or 1204A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Scion	xD	08-14	7002 or 1204A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Smart	Fortwo(433 Mhz)	08			1049	1040K	004 542 1518	1040K	E1101	KR5S122228002

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Smart	Fortwo(433 Mhz)	08-14			9214	2030K	000 905 7200	9066K	E1101	MRXMERCX1
Subaru	B9 Tribeca	06-07	7003	7020K	9081	1080K	28103AG00A	NO	A0301	MRXSUZ3MA4
Subaru	BRZ	13-14	7003	7020K	1218	1100K	28103-CA000	NO		PAXPMVC010
Subaru	Forester	08-14	7003	7020K	9203	VS950	28103AG01C	VS950	A0301	MRXSMD3MA4
Subaru	Impreza	08-13	7003	7020K	9203	VS950	28103AG01C	VS950	A0301	MRXSMD3MA4
Subaru	Legacy	04-07	7003	7020K	9081	1080K	28103AG00A	NO	A0301	MRXSUZ3MA4
Subaru	Legacy	08-14	7003	7020K	9203	VS950	28103AG01C	VS950	A0301	MRXSMD3MA4
Subaru	Outback	04-07	7003	7020K	9081	1080K	28103AG00A	NO	A0301	MRXSUZ3MA4
Subaru	Outback	08-14	7003	7020K	9203	VS950	28103AG01C	VS950	A0301	MRXSMD3MA4
Subaru	Tribeca	08-14	7003	7020K	9203	VS950	28103AG01C	VS950	A0301	MRXSMD3MA4
Subaru	XV Crosstrek	13-14	7003	7020K	9203	VS950	28103AG01C	VS950	A0301	MRXSMD3MA4
Suzuki	Equator	09-13	7001/HP	7020K	9204	2030K	43211-82Z10	NO	A1002	KOBHT05ATPDM
Suzuki	Forenza	07-08	7001-R/ HP-R	VS80	9153	VS950	43130-85Z03	VS950	A1002	MRXG53MA4S
Suzuki	Grand Vitara	07-13			9087	2010K	43130-54J21	NO	A1002	MRXNG33MA4S
Suzuki	Kizashi	10-13	7001/HP	7020K	1051	7020K	43130-57L00	VS70	A1002	KR5S180052015B
Suzuki	Reno	07-08	7001-R/ HP-R	VS80	9153	VS950	43130-85Z00	VS950	A1002	MRXG53MA4S
Suzuki	SX4	07-13			9087	2010K	43130-54J21	NO	A1002	MRXNG33MA4S
Suzuki	Verona	05-06			9082	2010K	43130-86Z20	NO	A1002	MRXTG224AM01
Suzuki	XL-7	05-06			9087	2010K	43130-54J21	NO	A1002	MRXNG33MA4S
Suzuki	XL-7	07-09	7001/HP	7020K	NA	1050K	43130-78J10	NO	A1003	MRXGMX272RS
Tesla	ALL	10-13			2112	2020K	6004985	TP416	**	TZSTPMS201
**For vehicle relearns, must utilize a Tesla relearn tool.										
Toyota	4 Runner	03-14	7002 or 1204A	7020K	1204	1110K	42607-33021	NO	A1101	PAXPMV107J
Toyota	Avalon	07-13	7002 or 1204A	7020K	1204	1100K	42607-06011/33011	NO	A1101	PAXPMV107J
Toyota	Avalon(Post 11/12)	13	7003	7020K	1218	1100K	42607-06020	NO	A1101	PAXPMVC010
Toyota	Camry	07-11	7002 or 1204A	7020K	1204	1100K	42607-06011/33011	NO	A1101	PAXPMV107J
Toyota	Camry	12-14	7003	7020K	1218	1100K	42607-06020	NO	A1101	PAXPMVC010
Toyota	Corolla	07-13	7002 or 1204A	7020K	1204	1100K	42607-06011/33011/33021	NO	A1101	PAXPMV107J
Toyota	Corolla (Post 8/13)	13-14	7003	7020K	1218	1100K	42607-06020	NO	A1101	PAXPMVC010
Toyota	FJ Cruiser	08-14	7002 or 1204A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Toyota	Highlander	07-14	7002 or 1204A	7020K	1204	1100K	42607-06011	NO	A1101	PAXPMV107J
Toyota	Highlander (Post 1/14) Smart Key	14	7003	7020K	1218	1100K	42607-06020	NO	A1101	PAXPMVC010
Toyota	Highlander-- (Post 1/14)-- RKE (Made in Canada)	14				NEW	42607-0R010			GQ4-51T
Toyota	Land Cruiser	05-14	7002 or 1204A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Toyota	Matrix	07-13	7002 or 1204A	7020K	1204	1100K	42607-06011/33011	NO	A1101	PAXPMV107J
Toyota	Prius	06-13	7002 or 1204A	7020K	1204	1100K	42607-06011	NO	A1101	PAXPMV107J
Toyota	Prius V	12-14	7002 or 1204A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Toyota	Prius C	12-14	7003	7020K	1218	1100K	42607-06020	NO	A1101	PAXPMVC010
Toyota	RAV 4	06-13	7002 or 1204A	7020K	1204	1100K	42607-06011	NO	A1101	PAXPMV107J

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Toyota	RAV4(Post 1/13)-- Smart Key	13-14	7003	7020K	1218	1100K	42607-06020	NO	A1101	PAXPMVC010
Toyota	RAV4(Post 1/13)-- RKE (Made in Canada)	13-14			NEW		42607-0R010			GQ4-51T
Toyota	Sequoia(20 Degrees)	04-07	7002 or 1204A	7020K	1204	1110K	42607-0C020	NO	A1101	PAXPMV107J
Toyota	Sequoia(40 Degrees)	04-07	7002 or 1204A	7020K	1203	1110K	42607-0C010	NO	A1101	PAXPMV1037
Toyota	Sequoia(20 Degrees)	08-14	7002 or 1206A	7020K	1206	1110K	42607-0C070/08010	NO	A1101	GQ4-32T
Toyota	Sequoia(40 Degrees)	08	7002 or 1206A	7020K	1206	1110K	42607-0C060	NO	A1101	GQ4-32T
Toyota	Sienna(20 Degrees)	06-14	7002 or 1206A	7020K	1206	1110K	42607-0C070/08010	NO	A1101	GQ4-32T
Toyota	Solara	06-08	7002 or 1204A	7020K	1204	1100K	42607-06011	NO	A1101	PAXPMV107J
Toyota	Tacoma(20 Degrees)	05-06	7002 or 1204A	7020K	1204	1110K	42607-0C020/AD020	NO	A1101	PAXPMV107J
Toyota	Tacoma(40 Degrees)	05-14	7002 or 1204A	7020K	1203	1110K	42607- 0C010/AD010/04010	NO	A1101	PAXPMV1037
Toyota	Tacoma(20 Degrees)	07-14	7002 or 1204A	7020K	1204	1100K	42607-06011	NO	A1101	PAXPMV107J
Toyota	Tundra(20 Degrees)	05-06	7002 or 1204A	7020K	1204	1110K	42607-0C020	NO	A1101	PAXPMV107J
Toyota	Tundra(40 Degrees)	05-06	7002 or 1204A	7020K	1203	1110K	42607-0C010	NO	A1101	PAXPMV1037
Toyota	Tundra(20 Degrees)	06-14	7002 or 1206A	7020K	1206	1110K	42607-0C070/08010	NO	A1101	GQ4-32T
Toyota	Tundra(40 Degrees)	06-11	7002 or 1206A	7020K	1206	1110K	42607-0C060	NO	A1101	GQ4-32T
Toyota	Venza	09-14	7002 or 1204A	7020K	1204	1100K	42607-06011	NO	A1101	PAXPMV107J
Toyota	Yaris	07-11	7002 or 1204A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Toyota	Yaris	12-14	7003	7020K	1218	1100K	42607-06020	NO	A1101	PAXPMVC010
Volkswagen	Beetle	08-10	7003	7020K	1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	CC	09-10	7003	7020K	1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	CC	11-14			9013	1096	3AA 907 275D	1096	E1204	OYGTSSRE4D
Volkswagen	EOS	07-14	7003	7020K	1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	GLI	08-09	7003	7020K	1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	Golf	10-11	7003	7020K	1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	GTI(Standard Hex)	06-11	7003	7020K	1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	GTI(O-ring Hex)	06-07	7003	7020K	1041	1031K	1K0907253E	NO	E1204	KR5S120123
Volkswagen	Jetta(Standard Hex)	06-11	7003	7020K	1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	Jetta Sportwagen	13			9018	1096	5Q0 907 275	1096	E1204	UNKNOWN
Volkswagen	Passat CC(Standard Hex)	06-10	7003	7020K	1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	Passat(433 Mhz)	12-13			9013	1096	3AA 907 275D	1096	E1204	OYGTSSRE4D
Volkswagen	Passat(O-ring Hex)	06-08	7003	7020K	1041	1031K	1K0907253E	NO	E1204	KR5S120123
Volkswagen	Phaeton(433 Mhz) (thru May 2007)	02-07			9007 or 9011	1090K	4D0 907 275C	1092	E1202	OYGTSSRE4B
Volkswagen	Phaeton(433 Mhz) (June 2007)	07-10			9007 or 9011	1090K	4F0 907 275B	1092	E1202	OYG TSSRE4TB

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Volkswagen	Phaeton(433 Mhz) Post June 2010	11-13			9011	1096	4F0 907 275D	1096	E1202	OYG TSSRE4TD
Volkswagen	Phaeton(315 Mhz)	03 -07			9004	1090K	4D0 907 275A	1092	E1202	OYGTSSRE3B
Volkswagen	R32	08	7003	7020K	1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	Rabbit(Standard Hex)	06-09	7003	7020K	1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	Rabbit(O-ring Hex)	06-07	7003	7020K	1041	1031K	1K0907253E	NO	E1204	KR5S120123
Volkswagen	Routan(433 Mhz)	09-10	7004	7020K	1043	1050K	7B0907253A	NO	E1205	KR5S180052020A
Volkswagen	Routan(433 Mhz)	11-12			9398	VS950	7B0907253C	VS950	E1205	MRXC4W4MA4
Volkswagen	Tiguan	09-11	7003	7020K	1053	1030K	1K0907253D	NO	E1205	KR5S120123
Volkswagen	Tiguan	12-13			9013	1096	3AA 907 275D	1096	E1204	UNKNOWN
Volkswagen	Touareg(433 Mhz)-- (December 2006)	03-07			9005	1090K	7L0 907 275B	1092	E1203	OYGTSSRE4PB
Volkswagen	Touareg(433 Mhz)-- (January 2007)	07-10			9007 or 9011	1090K	4F0 907 275B	1092	E1203	OYG TSSRE4TB
Volkswagen	Touareg	11-14			9011	1096	4F0 907 275D	1096	E1202	OYG TSSRE4TD
Volvo	C30(433 Mhz)	07-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	C30(433 Mhz)	11-13		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	C70(433 Mhz)	07-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	C70(433 Mhz)	11-13		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	S40(433 Mhz)	07-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	S40(433 Mhz)	11		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	S60(315 Mhz)	04-08	7003	7020K	9156	2010K	86517000	NO	E1301	MRXTG315AM04
Volvo	S60(315 Mhz)	09-10	7003	7020K	NEW	VS950	31200923	VS950	E1301	MRXSMD3MA4
Volvo	S60(315 Mhz)	09-10	7003	7020K	9156	2010K	OE Sensor Replacement	NO	E1301	MRXTG315AM04
Volvo	S60(433 Mhz)	11-14		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	S80(315 Mhz)	04-06	7003	7020K	9156	2010K	86517000	NO	E1301	MRXTG315AM04
Volvo	S80(433 Mhz)	07-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	S80(433 Mhz)	11-14		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	V50(433 Mhz)	08-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	V50(433 Mhz)	11		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	V70(315 Mhz)	04-07	7003	7020K	9156	2010K	86517000	NO	E1301	MRXTG315AM04
Volvo	V70(433 Mhz)	08-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	XC60	10-14		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	XC70(315 Mhz)	04-07	7003	7020K	9156	2010K	86517000	NO	E1301	MRXTG315AM04
Volvo	XC70(433 Mhz)	08-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	XC70(433 Mhz)	11-14		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	XC90(315 Mhz)	05-11	7003	7020K	9156	2010K	86517000	NO	E1301	MRXTG315AM04
Volvo	XC90(315 Mhz)	12-14	7003	7020K	NEW	VS950	31200923	VS950	E1301	MRXSMD3MA4
Volvo	XC90(315 Mhz)	12-14	7003	7020K	9156	2010K	OE Sensor Replacement	NO	E1301	MRXTG315AM04
Volvo	XC90(433 Mhz)	08		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
VPG	MV-1	11-13	7001-R/ HP-R	VS80	9315	VS950	SP000437	VS950	D0105	MRXFE3MAF4
Volvo Group	Volvo Bus	---	---	---	9010	VS9013 or VS9980	---	VS9013 or VS9980	---	OYGTSSRE4NB
Volvo Group	Prevost Bus	---	---	---	9010	VS9013 or VS9980	---	VS9013 or VS9980	---	OYGTSSRE4NB
Volvo Group	Nova Bus	---	---	---	9010	VS9013 or VS9980	---	VS9013 or VS9980	---	OYGTSSRE4NB

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
<p>DISCLAIMER: The data presented in this document is accurate to the best of our knowledge and is regularly updated with the latest data available in the marketplace. We encourage you to check back for the latest edition of this data, however, we cannot guarantee accuracy of the information provided. Also, please note that several vehicle applications require knowledge of the VIN number as the sensor design could have changed mid-model year. <u>PLEASE DO NOT POST THIS DOCUMENT ON ANY WEBSITE.</u></p>										